



AQ-Series Vertical Machining Centers



All specifications are subject to change without prior notice Verification of technical changes may be confirmed after receipt of order



Machine Features Overview

FANUC OiMF PLUS CNC Machine Control

High Speed – 30 HP - 15,000RPM Integral Motor Spindle – Big Plus CAT40 Spindle Taper

(32) Thirty-Two Pocket Standard Automatic Tool Changer. (40) Tools Optional Upgrade Available

Precision Hand Scraped Machine Metal to Metal Contact Points for Long Term Accuracy, Vibration Dampening and Extended Machine Life

Built in WELE iSmartTune Controller Package with Tool Life Monitoring and ATC Recovery Suite

Standard FANUC Package Includes 200 Block Look Ahead Function and 2MB Memory Standard

Embedded Machine Operator and Maintenance Manuals Resident on Controller


Dual Chip Auger with Lift Up Type Conveyor as Standard Feature. Includes Coolant Wash Down

1000 PSI Through Spindle Coolant Preparation





FANUC





FANUC OIMF PLUS Controller

15 Inch Touch Screen Platform with Built in Operation Supporter Package from WELE

FANUC's Upgraded Platform Includes a Full Suite Of Machine Monitoring and Operation Support Functions


Uses a Full Keyboard CNC Pendant with Hard Push Buttons

Standard FANUC OiMF PLUS Features

- Fine Surface Technology Set Optimal Parameters for Roughing, Semi-Finishing, and Finishing
- Al Contour Control II, Smooth Tolerance Control, and Control Nano Interpolation
- Built in Reporting that that Monitors Productivity and Tool Life
- Fast Cycle Time Technology Set of Servo Functions to Reduce Cycle Time. Acc/Dec Based on Load Inertia, Reduction in Processing Time
- FANUC Picture Allows Generation of Custom Control Objects – WELE iSmartTune
- Smart Servo Control Real Time Optimization Suite
- A Simplified Repair Process with Step-Through Procedure for Common Issues such as ATC Recovery
- On Board Storage and Display of all Machine Maintenance and Operation and Tooling Manuals



FANUC






Machine Specifications

X Axis Travel - AQ1265	1,200 mm (47.2")
X Axis Travel - AQ1465	1,400 mm (55.1")
X Axis Travel - AQ1665	1,600 mm (63.0")
Y Axis Travel	650 mm (25.6")
Z Axis Travel	610 mm (24.0")
Distance from Spindle Nose to Table Top	150 - 760 mm (5.9" - 29.9")
Table Height From Plant Floor	900 mm (35.4")
Spindle Taper	CAT40 (Big PLus)
Spindle Motor	30HP
Spindle Speed	15,000RPM
Spindle Type	Built in Motor
Rapid Feedrate (X & Y Axes)	36 m/min (1,417 ipm)
Rapid Feedrate (Z Axis)	30 m/min (1,181 ipm)
Chain Type ATC	32 Pockets (OPT. 40)
Maximum Tool Diameter with Tool in Adjacent Pocket	80 mm (3.1")
Maximum Tool Diameter with Adjacent Pocket Empty	150 mm (5.9")
Maximum Tool Length from Gage Line	250 mm (9.8")
Maximum Tool Weight	7 kg (15.4 lb)
Tool Taper	CAT40 Big Plus
Pull Stud	ANSI CAT40
Tool Selection	Random
Tool Access	Bi-Directional
Positioning Accuracy (JIS)	±.005 mm (±.0002")
Repeatability (JIS)	±.003 mm (±.0001")
Total Power Required	3 Phase ±10% 220 V (35 kVA)
Power Supply Frequency	50 / 60 Hz
Axis Guideways	Linear Roller Guideway
Coolant Tank Capacity (Including CTS Tank)	147.2 gal
Flood Coolant (Gallons per Minute)	20 gal





Power & Torque CAT40 15,000 Built in Motor



Benefits to Built-In Spindle Design:

G.4 Spindle Balance Specification Achieved as WELE Standard vs G1 Industry Standard – Increased Tool Life and Superior Surface Finish

Reduction in External Connections, Cabling and Wiring

Increased Powerband to High Speed - Increased Torque at Low RPM Range

No Motor Coupling to Introduce Outside Vibration



Factory Balance Stand G.4 Specification



WELE Precision Hand Scraping – All Metal Contact Surfaces






Fanuc OIMF-PLUS Control Package

Absolute or incremental programming	G90, G91	Memory card interface	CF card and PCMCIA card attachment is
Actual cutting feedrate display			required.
Addition of Custom macro common variables	#100~#199, #500~#999	Multi-language display	
Addition of Workpiece coordinate system	48 pairs	Number of registerable programs	1000 programs
Al contour control II	Look-ahead blocks 200	Operator message display	
Air blow on	M07	Operator message history display	
Alarm display		Optional block skip	
Alarm history display		Optional chamfering/corner R Overtravel	
Auto power off		Parameter setting and display	
Automatic acceleration/deceleration	linear	Parameter setting support screen	
Automatic corner deceleration		Parity check	
Automatic corner override	G62	Part program editing	
Automatic return to reference position	G28	Part program storage size	2M byte
Backlash compensation		Peck drilling cycle	G73, G83
Backlash compensation for each rapid		Plane selection	G17, G18, G19
traverse and cutting feed		Playback	
Bell-type acceleration/deceleration		Polar coordinate command	G15, G16
after cutting feed interpolation		Positioning	G00
Calling subprogram stored in	M198	Program cide	EIA/ISO
external memory		Program comment display	Program name 31 characters
Circular interpolation cw(ccw)	G02, G03	Program end	M02, M30
Helical interpolation cw(ccw)		Program file name	32 characters
Clock function		Program protect key	
Constant surface speed control	A surge (Outling to E surge)	Program restart	
Control axes	4 axes (Option to 5 axes)	Program stop / Optional stop	M00, M01
Control axis detach	669,669	Programmable data input	G10, G11
Coordinate system rotation mode	G68, G69	Programmable mirror image	G50.1 / G51.1
Current position display		Rapid traverse bell-shaped	
Custom macro Cutter compensation	G40, G41, G42	acceleration/deceleration	
•	0, 10%, 20%, 30%, 200%	Rapid traverse override	F0, 25%, 50%, 100%
Cutting feedrate override	0, 10%, 20%, 30%, 200%	Reference position return function	
Decimal point programming/pocket calculator		Rigid tapping	M29
type decimal point programming		Rigid tapping bell-shaped	
Direct input of workpiece origin offset value measured		acceleration/deceleration	
offset value measured		Rotary axis designation RS-232C interface	
Display of hardware and software configuration		Run hour and parts count display	
DNC	CF card or RS-232C or Data Server attachment	Scaling cancel	G50 / G51
DNC operation	required	Screen hard copy	3507 351
Dry run		Self-diagnosis function	
Dwell, exact stop	G04	Sequence number	N8 digit
Dynamic display langauge switching		Servo information screen	ite digit
Dynamic graphic display		Servo setting screen	
Emergency stop		Simultaneously controlled axes	4 axes
Ethernet interface	Program transfer	Single block	
Exact stop	G09	Single direction position	G60
Exact stop mode	G61	Skip function	G31
Extended part program editing		Software stroke check 1	
External deceleration		Software stroke check 2, 3	
External machine zero point shift		Special fixed cycle	G34, G35 (macro control is required)
External message		Spindle axes	1 axes
Feed per minute	G94	Spindle information screen	
Feed per revolution	G95	Spindle orientation	M19
Feedrate override reset		Spindle output switching function	
		Spindle override	50%, 60%, 70%, 120%
Fine surface machining		Spindle serial output	
Fixed cycle	G74, G76, G80, G81, G84-G89	Spindle setting screen	
Follow up		Spindle speed function	
FSSB High speed rigid tapping		Spindle synchronous control	
Handle interruption		Status display	
Help function		Stored pitch error compensation Stroke check before movement	
High-speed and high-precision machining	HRV3 Control	Sub program call	10 folds nested
Ilelical interpolation		Thread cutting	G33 (macro control is required)
Increment system C	0.001mm / 0.0001 inch / 0.001 deg	Tool function	T8 digit
Input in mm or inch	G20, G21	Tool length measurement	10 digit
JOG feed		Tool length offset	
Linear interpolation	G01	Tool life management	
M, S, T function		Tool offset increase or decrease	G45~G59
Machine lock	All axes	Tool offset memory C	
Macro executor/C language executor		Tool offset pairs	400 pairs
Manual absolute on and off		Tool radius offset	·
Manual guide 0i		USB interface	Only data input and output (not DNC)
Manual handle feed	1 unit	Workpiece coordinate system	G54~G59
Manual handle feed rate	X1, X10, X100	Workpiece coordinate system preset	
Manual reference position return		Z lock	
Max. programmable dimension	+/- 9 digits		
MDI Operation			










	А	В	С	D
AQ1265	1400			
AQ1465	1600	650	75	100
AQ1665	1750			


T-Slot Specification



AQ Series - High Speed Vertical Machining Centers





AQ1665






Retention Knob & Tool Assembly CAT40









Shipping Dimensions - Reference

AQ1265 Dimensions


Crate #1: 3550mm x 2320mm x 2550mm @ 7,000KGS Crate #2: 4390mm x 1150mm x 2470mm @ 1,800KGS

AQ1465 Dimensions

Crate #1: 3950mm x 2320mm x 2550mm @ 7,700KGS Crate #2: 4590mm x 1150mm x 2470mm @ 1,800KGS

Machine Weight

AQ1265 Weight: 6,500KG AQ1465 Weight: 7,200KG AQ1665 Weight: 7,700KG











Productivity Enhancements









3.2.1 Power and grounding

- a. AC line Voltage: 3 phases AC 220V +/- 10% (AC 380V, 400V etc. must through transformer)
- b. Frequency: 50 or 60 Hz +/- 1%
- c. Power capacity: AQ1265/AQ1465/AQ1665: 35KVA
- d. Main circuit breaker:

model	Voltage	Current capacity	Main breaker
AQ1265/AQ1465/AQ1665	220V(for USA/Asia/Japan)	100A	150A
	400V (for Europe)	100A	

- e. The cross-section area of Power line cable: 38mm²
- f. The colors of power line cables should be assigned by CE regulations.
- g. The outside terminal of power line cables should be protected by fuse or breaker.
- h. The power line cables should **NOT** be connected with other machines, but be connected independently.
- i. The cross-section area of grounding wire: 22mm^2 ; the grounding resistor should be less than 50 Ω . The color of grounding wire must be yellow-green.
- j. The grounding method of multiple machines is shown as Figure 3-1.
- k. Ambient temperature: 0°C~45°C. Ambient humidity: Under 90%

3.2.2 Compressed air

- a. Compressed air must be filtered to keep it clean and dry (dew point, below 7kgf/cm²; 10°C).
- b. The required pressure of compressed air is 4~7 kgf/cm². Make sure the supply of compressed air satisfy the capacity requirement. (One-hp air compressor could provide 90 L/min air flow rate, and it is approximately enough.) Furthermore, air compressor should not branch the use ends excessively, or the instantaneous pressure varieties will cause the insufficient machine pressure alarm.
- c. The size of quick couplings at the air inlet is 3/8".

